

OFFICE OF THE SUB DIVISIONAL OFFICER


PANCHAYATI RAJ LAMBI

Email id:sdoprlambi@gmail.com

Building Safety Certificate

No.....149.....
Date.....06/09/2022.....

- (a) I have visited the **BABA ISHER SINGH (NANAKSAR) SEN. SEC. PUBLIC SCHOOL KATTIANWALI BLOCK MALOUT** on 01.09.2022 and inspected of from all angles of safety and I find it fit for the normal use of a school Building
- (b) In case any addition alteration or expansion and modification to this building is to be carried out, the same be carried out under the supervision of a technically qualified engineer and this certificate may again be obtained of the stability and safety of the building
- (c) In case the building is affected by flood or if there settlement of walls foundation of sagging roof etc. immediately inspections of the stability and safety of the building by Engineer.
- (d) This building can be safely occupied for normal use up to **31.08.2023**


Sub Divisional Officer,
Panchayati Raj,
Lambi. 18